DOC-280921-HCW



17 April 2020

Project No. 19126590.L49.A1

ESB Networks

Engineering and Major Projects One Dublin Airport Central **Dublin Airport** Cloghran County Dublin K67 XF72

RE ESB SITE 49 POOLBEG TO RINGSEND TF4 110KV CABLE FLUID LOSS: RECOMMENDATIONS

To whom it may concern

ESB Engineering and Major Projects (ESB) commissioned Golder Associates Ireland Limited (Golder) to complete a Preliminary Site Assessment (PSA) for historical loss of fluid from a high voltage (110 kV) cable run located between Poolbeg and Ringsend TF4, Dublin ('Site 49') (hereafter referred to as the 'Site').

The PSA was produced in-line with current EPA guidance (Guidance on the management of contaminated land, 2013). The findings of the PSA were presented in our report reference 19126590/49.A.1 dated 17 April 2020.

The risk assessment completed for this site did not identify viable pollutant linkages. Golder does not recommend any follow up actions in relation to the loss of 210 L of cable fluid in August 2006 at this site as detailed in the report referenced above.

Yours sincerely,

Golder Associates Ireland Limited

Senior Hydrogeologist

Geo Environmental Director

EMcA/TM/mb

Golder Associates Ireland Limited Town Centre House, Dublin Road, Naas, Co. Kildare, W91 TD0P Ireland

Registered in Ireland Registra ion No. 297875 Town Centre House, Dublin Road, Naas, Co. Kildare, W91 TD0P, Ireland

Directors: S. Copping, A. Harris, DRV Jones

VAT No.: 8297875W

golder.com

T: +353 45 810 200