

Innovation House DCU Alpha Old Finglas Road Dublin D11 KXN4

> Tel: 01 653 3170 www.geosyntec.eu

7th April 2020 Our ref: GCU0257001/GW/JW

ESB Networks **Engineering Major Projects** One Dublin Airport Central Dublin Airport Cloghran Co. Dublin

## Subject: Historic Cable Fluid Losses - Location 24 **Recommendations from Preliminary Site Assessment**

Dear Sir/Madam

We refer to our Preliminary Site Assessment (PSA) report on the historic loss of cable fluid in Booterstown, Co. Dublin (Location 24) dated 7th April 2020. The PSA identified the following potential receptors and preliminary risk categories linked to the cable fluid loss<sup>1</sup>:

•	Booterstown Marsh SPA	-	Moderate
•	Booterstown Stream	37	Moderate
•	Dublin Bay SAC/SPA	<b>*</b> :	Moderate
٠	Water mains	÷	Low
•	Bedrock aquifer	-	Low

With a view to confirming the above preliminary risk categories, we would make the following recommendations:

Assess whether there is residual cable fluid (as LNAPL) in the cable trench at the leak location. This may be best achieved by excavating one or two slit trenches perpendicular to the line of the cable trench in close proximity to the leak location and recording field evidence of impact by cable fluid. If LNAPL is not observed, then consideration should be given to collecting soil samples from the slit trenches and submitting them for laboratory analysis for linear alkyl benzenes and potential breakdown products;

<sup>&</sup>lt;sup>1</sup> The preliminary risk categories were determined by applying the risk assessment methodology outlined in CIRIA publication C552 (2001).



Quality ISO 14001 Envrionment OHSAS 18001 Health & Safety Company Registered in Ireland No: 906304 Registered office - as above



- Monitor water quality in Booterstown Marsh SPA, Booterstown Stream and Dublin Bay SAC/SPA down-gradient of the leak location for linear alkyl benzenes and potential breakdown products;
- Refine the preliminary risk assessment based on the findings of these tasks.

Depending on the findings of the above tasks, further intrusive investigation may be needed to adequately refine the Conceptual Site Model and risk assessment.

Yours sincerely for Geosyntec Consultants Ltd

Principal Environmental Engineer